LORD DCP Errata

3DM-GX3[®]

Data Communications Protocol Errata @ 2/2/2015

Errata

The descriptor set indicates that 0C3A and 0C3B are supported; however these commands do not work correctly in some versions of firmware:

FW version 2.0.06

GX3-25 Implements the C3A, C3B commands but the values read back are not the values written (they are a pre-calculated value that is used internally)

GX3-15 Includes the 0C3A and 0C3B commands in descriptor set but not supported (NACK'ed)

FW version 2.0.10

GX3-25 0C3A and 0C3B commands work correctly

GX3-15 Includes the 0C3A and 0C3B commands in descriptor set but not supported (NACK'ed)

Support

LORD MicroStrain[®] support engineers are always available to expand on this subject and support you in any way we can.