

WSDA[®]-1000 and WSDA[®]-MIL



Firmware Upgrades

Overview

LORD MicroStrain[®] is continually improving the functionality of its [WSDA[®]-1000](#) and [WSDA[®]-MIL](#) Wireless Sensor Data Aggregators. The resulting firmware upgrades are made available from time to time; please contact your LORD MicroStrain[®] support engineer to determine if an upgrade is available for your particular device. We recommend that users upgrade their devices to the latest available firmware to take advantage of these improvements and to minimize operating issues. This technical note provides step-by-step upgrade instructions. Live Connect version 2.1.3 or greater is required and it is assumed that the user has familiarity with the device's operation.

Step-by-step

- Contact your LORD MicroStrain[®] support engineer and download the upgrade file.
- Launch Live Connect.
- Click to highlight your WSDA.
- Click View and the WSDA Control Panel will launch in your browser.
- Enter your Login.
- Enter your Password.
- Click Authenticate and the About window of the WSDA Control Panel will appear.
- Under the Tools menu, click OS Upgrade and the OS Upgrade window will appear.
- Click Browse and navigate to the upgrade file.
- Click Upload, the upgrade will commence and a successful message will follow.



Support

LORD MicroStrain[®] support engineers are always available to expand on this subject and support you in any way we can.